

# Accordance Systems Inc.

2F, No.31, Sec.6, Hsin Yi Road, Taipei, Taiwan

Tel: +886-2-2726-3239

Fax: +886-2-2728-1322

[Http://www.accordance.com.tw](http://www.accordance.com.tw)

E-mail:[sales@accordance.com.tw](mailto:sales@accordance.com.tw)

---

Date: Aug. 16<sup>th</sup>, 2011

## Illustration of ARAID 3500 Firmware amendment

Previously, the standard ARAID 3500 Firmware was v1000707. We recently amended the firmware, so the standard Firmware of ARAID 3500 is now become **v110812**.

**v110812** firmware amends for below two problems which won't occur again:

1. After powering on PC (M/B) and ARAID 3500, M/B BIOS sometimes couldn't detect ARAID 3500 and cause ARAID 3500 failure problem occurred. Below M/B list was the M/B that we found out have above mentioned problem.
  - 1) ASUS and Gigabyte M/B.
  - 2) Intel DP67BG M/B and install Intel inf\_9.2.0.1030 driver.
  - 3) Advantech PCA-6101VG M/B → this M/B will reset 3 times.
2. During power on process, few HDD were easily to be determined as FAIL problem.